




01 WALKWAY RESTORATION
SECTION
1/2"=1'-0"




02 BOARDWALK
SECTION
1/2"=1'-0"




03 STACKED BOULDER WALL
DETAIL
1/2"=1'-0"




04 PARKING LOT AT CUT WALL CONDITION (<3')
SECTION
1/2"=1'-0"




05 PARKING LOT AT CUT WALL CONDITION (>3')
SECTION
1/2"=1'-0"




06 PARKING LOT AT FILL WALL CONDITION
SECTION
1/2"=1'-0"




07 ENTRY DRIVE AT CUT WALL CONDITION
SECTION
1/2"=1'-0"




08 PARKING LOT AT DENSE EXISTING VEGETATION
SECTION
1/2"=1'-0"



09 PARKING LOT AT SPARSE/NEW VEGETATION
SECTION
1/2"=1'-0"



10 PARKING LOT AT PEDESTRIAN WALKWAY
SECTION
1/2"=1'-0"



11 FREE STANDING STONE WALL
SECTION
1/2"=1'-0"

NOTE:
OCCURS IN APPROXIMATELY 60%
OF FLUSH CURB SITUATIONS

NOTE:
OCCURS IN APPROXIMATELY 40%
OF FLUSH CURB SITUATIONS