















The new
Feature

The new
Feature

16' SANITARY SEWER EASEMENT
(VOL. 4167, PAGES 1853-1860 O.P.R.)

-  LIVE OAK LOCATED BY SURVEY
-  CEDAR ELM LOCATED BY SURVEY
-  TREES NOT LOCATED IN SURVEY, BUT OBSERVED ON SITE, LOCATION NOT PRECISE
-  HERITAGE TREE OF EXCEPTIONAL QUALITY. EVERY EFFORT SHOULD BE MADE TO SAVE THESE TREES
-  HIGH QUALITY TREE THAT WILL ADD SUBSTANTIAL VALUE AND CHARACTER TO THE PROJECT
-  NOTABLE TREE OF SIGNIFICANT VALUE WITH POTENTIAL TO MATURE INTO AN EXCEPTIONAL TREE
-  GOOD QUALITY TREE THAT IS WORTH SAVING BUT NOT WORTH MAJOR PLANNING EFFORTS

-  LIVE OAK LOCATED BY SURVEY
-  CEDAR ELM LOCATED BY SURVEY
-  TREES NOT LOCATED IN SURVEY, BUT OBSERVED ON SITE, LOCATION NOT PRECISE
-  HERITAGE TREE OF EXCEPTIONAL QUALITY. EVERY EFFORT SHOULD BE MADE TO SAVE THESE TREES
-  HIGH QUALITY TREE THAT WILL ADD SUBSTANTIAL VALUE AND CHARACTER TO THE PROJECT
-  NOTABLE TREE OF SIGNIFICANT VALUE WITH POTENTIAL TO MATURE INTO AN EXCEPTIONAL TREE
-  GOOD QUALITY TREE THAT IS WORTH SAVING BUT NOT WORTH MAJOR PLANNING EFFORTS